

BELZONA PROTECTS HOG FUEL SCREW CONVEYOR

ID: 6009



PROBLEM

The worn auger would be replaced periodically due to the flights being too thin. The manufacture and replacement of these augers were expensive. The life of the auger was hard to predict due to the varying raw material supplied and the changing demand. Downtime was not a good option when supplying the critical nature of the Boilers.

APPLICATION SITUATION

The raw wood supplied to this Pulp and Paper Mill used to burn in the Boiler for process steam was transported to the Boiler house via this auger. The abrasive nature of the media would wear the base of the flighting on this auger.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-14 and Belzona product Instructions For Use.

BELZONA FACTS

Because of the critical nature of this equipment, a spare auger shaft or screw conveyor was kept on standby. This allowed the application to be performed with no downtime. Because the auger could be coated on site, the cost of protecting and improving the auger far outweighed the replacement and shipping costs of the auger.

INDUSTRY

Pulp & Paper

LOCATION

Montana, USA

APPLICATION DATE

2004

PRODUCTS

Belzona 9111 (Cleaner Degreaser)

Belzona 1812 (Ceramic Carbide FP)

SUBSTRATE

Carbon Steel

PHOTOS

1. Grit Blasting of auger
2. Belzona 1812 applied to base of flighting
3. Shipping wrap placed over Belzona 1812 to smooth surface
4. Full length of auger protected and improved

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

