

BELZONA REPAIRS NATURAL GAS VALVE

ID: 602



PROBLEM

Gas leaks had been worsened by traditional weld repairs.

APPLICATION SITUATION

Natural gas valve

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-1.

BELZONA FACTS

Belzona successfully solved this serious problem with a simple and fast technique, avoiding heat distortion to the surface and at a low cost.

INDUSTRY

Oil & Gas

LOCATION

Oil and gas production company, Egypt

APPLICATION DATE

February 2003

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Cast iron

PHOTOS

1. General view of the valve
2. Traditional welding failed causing more leakage
3. Surface preparation
4. Application completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

