

SEAWATER FIRE PUMP REPAIR WITH BELZONA

ID: 6033



PROBLEM

The customer was having problems with severe corrosion on the pumps due to them being idle for months at a time, often after only a few years of use they were being replaced with new ones.

APPLICATION SITUATION

Fire pump using sea water

APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet CEP-3.

BELZONA FACTS

For a fraction of the cost of a new pump the customer is now having his pumps repaired with Belzona products. This not only offers significant savings, but the coated pumps last in service 3 times longer than the originals.

INDUSTRY

LOCATION

Houston, TX, USA

APPLICATION DATE

March 2012

PRODUCTS

Belzona 1111 (Super Metal)
Belzona 1341 (Supermetalgilde)

SUBSTRATE

Carbon Steel

PHOTOS

1. Severely corroded pump
2. Corroded pump end-cover
3. Pump after the application
4. Pump end-cover after the application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

