

BELZONA STOPS LEAKS AND PROTECTS PARKED CARS

ID: 6043



PROBLEM

Cooling tower line drains were leaking and causing damage to the paint of vehicles parked below. Aesthetics were important to the client. Not only did they need the leak stopped, they also needed a solution that would not be an eye-sore to their tenants.

APPLICATION SITUATION

Cooling tower drain lines.

APPLICATION METHOD

The application was carried out with a modified version of Belzona Know-How System Leaflet VPF-15.

BELZONA FACTS

The Belzona application was carried out in half a day and the customer was in service during the repair. Alternative methods would have taken the cooling tower offline for 2-3 days, leaving tenants uncomfortable and the cost much more expensive.

INDUSTRY

Buildings & Structures

LOCATION

Houston, TX, USA

APPLICATION DATE

December 2015

PRODUCTS

Belzona 1161 (Super UW-Metal)
Belzona 5111 (Ceramic Cladding)

SUBSTRATE

Carbon Steel

PHOTOS

1. Before Application
2. After surface preparation
3. Belzona 1161 used to apply cap to leaking area
4. Complete project with Belzona 5111 used to match the existing paint on the line

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

