



BELZONA REPAIRS BEAM ABOVE PAPER MACHINE

ID: 6046



PROBLEM

Badly corroded beam that was rusted completely through. The vibration of the paper machine was causing rust to fall on the paper sheet and break the paper causing the machine to shut down several times a day.

APPLICATION SITUATION

Support beam above paper machine.

APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet TCC-5.

BELZONA FACTS

The outage had already started when the mill found out what was causing the issues. The Belzona application cost \$16,000 USD and three days to be completed, compared to \$30,000 USD and two weeks to build the beam and cut the wall out to install, which would result in a more costly downtime.

INDUSTRY

Buildings & Structures

LOCATION

Campti, LA, USA

APPLICATION DATE

November 2015

PRODUCTS

Belzona 1111 (Super Metal)
Belzona 5892

SUBSTRATE

Carbon Steel

PHOTOS

1. Corroded beam
2. Beam after SP-10 blast
3. Beam after rebuild and coating
4. Beam after coating

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

