

BELZONA REBUILDS CLARIFIER RUNNING TRACK

ID: 605



PROBLEM

The wheels had caused between 2mm and 10mm wear to the concrete and were not running smoothly.

APPLICATION SITUATION

The running track alongside the clarifier

APPLICATION METHOD

The track was rebuilt with Belzona® 4111 in accordance with Belzona Know-How System Leaflet FPA-1.

BELZONA FACTS

Client chose Belzona over competitive system due to the total technical and application package put together by the Belzona Distributor.

INDUSTRY

Water / Wastewater

LOCATION

Sewage farm - Switzerland

APPLICATION DATE

2003

PRODUCTS

Belzona 4111 (Magma-Quartz)

Belzona 4911 (Magma TX Conditioner)

SUBSTRATE

Concrete

PHOTOS

1. The clarifier track
2. Conditioning the surface with Belzona 4911
3. Rebuilding with Belzona 4111
4. The finished track

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

