



BELZONA COLD REPAIR TO LEAKING PIPE JOINT

ID: 6067



PROBLEM

On investigation it was found that pipe was leaking at the joint and fittings were corroded.

APPLICATION SITUATION

Tenant on 10th floor of block of Flats was experiencing a leak from flat above causing water damage.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet VPF-11 application method a).

BELZONA FACTS

Due to the location and access of the leak, hot work could not be carried out. The Belzona cold applied application was the ideal and cost effective solution. Belzona has excellent adhesion to the different metals involved.

INDUSTRY

LOCATION

City Council, Newcastle, UK

APPLICATION DATE

March 2016

PRODUCTS

Belzona 1212

SUBSTRATE

Steel pipe, Copper Pipe & brass fittings

PHOTOS

1. Pipe/Joint location
2. Close up of corroded joint
3. Joint sealed/repaired

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

