

BELZONA REPAIRS LEAKING HEXANE PROCESS PIPE

ID: 6068



PROBLEM

Customer had been using a temporary pipe wrap which did not offer a permanent solution. Leaking of the pipe was a Health & Safety issue due to the volatility of the Hexane product flowing through the process pipework.

APPLICATION SITUATION

Customer had a through wall leak on a Hexane supply line to their manufacturing process.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet VPF-11 application method a). The process plant was isolated and pipework drained before carrying out surface preparation and application of Belzona 1111.

BELZONA FACTS

Due to the temporary nature of the repair method that they were using, the Belzona solution removed the Health & Safety risk whilst also providing a permanent repair.

INDUSTRY

General Industry

LOCATION

Adhesive Manufacturer, Cramlington, UK

APPLICATION DATE

February 2016

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Carbon Steel

PHOTOS

1. Temporary pipe wrap
2. Removal of temporary pipe wrap
3. Permanent Belzona repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

