


BELZONA PROTECTS BOX GUTTERS

ID: 6111



PROBLEM

The client was about to take possession of a newly constructed office block. However, the gutters were leaking at multiple points around the building and so they were refusing to take ownership until the roof was watertight. It was thought that the joints and drain points were at fault. The main contractor had tried to seal these with a bituminous coating, which was ineffective and so needed to be removed. Belzona were approached for a liquid applied solution that could be backed by a warranty.

APPLICATION SITUATION

Plastic Coated Box Gutters.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets RPA-6 and RPA-8.

BELZONA FACTS

With so many people already working in the building, the water based Belzona 3111 system was ideal. A seamless flexible membrane was applied along the full length of all of the roof gutters and up the joints of the parapet wall with a total length over 320 metres. Once completed, the contractor issued a warranty so that the client finally had the confidence to take ownership of the building.

INDUSTRY

Buildings & Structures

LOCATION

Corporate Office, Teesside, UK

APPLICATION DATE

2013

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Plastic coated steel.

PHOTOS

1. Building front aspect
2. Typical gutter on initial inspection
3. Application of Belzona 3111 underway
4. Application completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

