


CHEMICAL BUILDING ROOF LEAK REPAIRED BY BELZONA 3111

ID: 6118



PROBLEM

Leaks at roof joints allowed water to leak through causing damage to the chemicals stored below.

APPLICATION SITUATION

Chemical plant Roof

APPLICATION METHOD

Application was carried out in accordance with Belzona Know How System Leaflet RPA-1 and RPA-2. The fully reinforced Belzona 3111 System was applied to bridge all joints on the roof.

BELZONA FACTS

Belzona 3111 provides excellent waterproofing and weatherproofing properties, ability to be applied at problem areas making it a cost effective solution on all sizes and types of roof.

INDUSTRY

Chemical & Petrochemical

LOCATION

Chemical Company, Thailand

APPLICATION DATE

November 2011

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Concrete

PHOTOS

1. Overall picture of the area that need to be repaired
2. Belzona 3111 was applied
3. First coat of Belzona 3111 incorporating Belzona 9311 Reinforcement sheet being applied
4. Ongoing application of Belzona 3111 system to all roof joints

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

