

BELZONA SEALS NEW PIPES IN HOTEL WATER RESERVOIR

ID: 6168



PROBLEM

New pipes drilled into water reservoir needed to be anchored and sealed to the tank wall.

APPLICATION SITUATION

Hotel water reservoir needed new piping.

APPLICATION METHOD

Application carried out in accordance with Belzona Know How System Leaflets FPA-5

BELZONA FACTS

The customer was looking for reliable solution since on previous experience leaks had occurred around the pipes. Belzona 4111 provides high bond strength without shrinking enabling a secure leak free installation.

INDUSTRY

Buildings & Structures

LOCATION

Hotel, Israel

APPLICATION DATE

2013

PRODUCTS

Belzona 4111 (Magma Quartz)

SUBSTRATE

Carbon Steel , Concrete

PHOTOS

1 & 2. Internal application to secure new pipes

3 & 4 External fixing of pipes

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

