

BELZONA ELIMINATES TRIP HAZARD FROM DRAIN COVERS

ID: 6185



PROBLEM

Existing drain covers were proud of surface creating a potential trip hazard.

APPLICATION SITUATION

Drain covers in various areas of shopping centre.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System leaflets FPA-1 & FPA-8. Concrete was ground away and Belzona 4111 used to re-install plates at ground level. Plates were then coated with Belzona 4411 Granogrip to provide slip resistance.

BELZONA FACTS

The finished outcome eliminated the trip hazard and installation did not impact on normal operations around the shopping centre.

INDUSTRY

Buildings & Structures

LOCATION

Shopping centre, Bankstown, Australia

APPLICATION DATE

May 2004

PRODUCTS

Belzona 4111 (Magma Quartz)
Belzona 4411 (Granogrip)

SUBSTRATE

Concrete

PHOTOS

1. The raised drain plate
2. Belzona 4111 to rebuild drain
3. The plate fixed in place
4. Coated with Belzona 4411

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

