

BELZONA WATERPROOFS CORPORATE HEADQUARTERS

ID: 6188



PROBLEM

Improper sealing of the roof structure of the high rise building was allowing water to leak into the offices below.

APPLICATION SITUATION

Flat Roof of headquarters building.

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet RPA-1. The roof of the building was cleaned using a high pressure water wash and detergent. Once Cleaned, cracks were filled and sealed using Belzona 4151. The entire roof was then sealed using the fully reinforced Belzona 3111 system to prevent any future water ingress.

BELZONA FACTS

A high performance waterproofing system was required to protect the offices of this prominent travel company. Belzona was chosen for its ease of application and solvent free nature which kept disruption to the offices to a minimum.

INDUSTRY

Buildings & Structures

LOCATION

Travel company headquarters, Brisbane, Australia

APPLICATION DATE

July 2012

PRODUCTS

Belzona 4151 (Magma Quartz Resins)
Belzona 3111 (Flexible Membrane)

SUBSTRATE

Concrete

PHOTOS

1. The existing roof 2. Power washing in progress 3. Cracks exposed and sealed with Belzona 4151 4. The finished application after application of the Belzona 3111 system

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

