

DAMAGED RUBBER LINING RESTORED

ID: 619



PROBLEM

Peeled-off lining at welding edges causing under lining corrosion due to sea water penetration between the rubber sheets.

APPLICATION SITUATION

Water media filter

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-3.

BELZONA FACTS

Belzona performed easy, onsite repair of the existing lining. No new lining is required and all seams between the rubber sheets were well sealed and protected.

INDUSTRY

Water / Wastewater

LOCATION

Water treatment plant, Egypt

APPLICATION DATE

October 2001

PRODUCTS

Belzona 2221 (MP-Fluid Elastomer)

SUBSTRATE

Rubber and carbon steel.

PHOTOS

1. Peeled-off lining
2. Surface preparation of rubber at the welded seams areas
3. Problem solved
4. Sealed seams

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

