

BELZONA REPAIRS CONCRETE AFTER BOLLARD REMOVAL

ID: 6190



PROBLEM

Removal of bollards left rough concrete substrate that was a trip hazard.

APPLICATION SITUATION

Damaged concrete in 48 areas where bollards were removed

APPLICATION METHOD

Application was carried out in accordance with Belzona Know How System Leaflet FPA-1.

BELZONA FACTS

Ability to feather edge the Belzona 4111 enabled damaged areas to be quickly and simply levelled to eliminate trip hazard.

INDUSTRY

Buildings & Structures

LOCATION

Shopping Centre, Bankstown, Australia

APPLICATION DATE

September 2004

PRODUCTS

Belzona 4111 (Magma Quartz)

SUBSTRATE

Concrete

PHOTOS

1.Damaged concrete

2.Conditioner applied

3.Mixing Belzona 4111

4. Applying Belzona 4111

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

