

BELZONA KEEPS TENANTS DRY AND HAPPY

ID: 6197



PROBLEM

Cracks in the flat roof were allowing water to penetrate into the offices below.

APPLICATION SITUATION

High Rise Office complex in the Brisbane Central Business District.

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet RPA-1. After high pressure washing and drying the roof, cracks and defects revealed during the cleaning process were filled using the Belzona 4151 or Belzona as appropriate. A fully reinforced Belzona 3111 system was then applied over the entire roof area.

BELZONA FACTS

The Belzona 3111 system was chosen as it provided the required level of performance and longevity. The client was looking to achieve a long term solution with minimal disruption

INDUSTRY

Buildings & Structures

LOCATION

office complex, Brisbane, Queensland, Australia

APPLICATION DATE

July 2012

PRODUCTS

Belzona 4111 (Magma Quartz)
Belzona 4151 (Magma Quartz Resins)
Belzona 3111 (Flexible Membrane)

SUBSTRATE

Concrete

PHOTOS

1. Original roof condition
2. Cracks in roof
3. Defects in the roof that needed repair
4. The finished application after application of the Belzona 3111 system

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

