

BELZONA EXPANSION JOINT SEALANT FOR CORPORATE OFFICE

ID: 62



PROBLEM

Existing sealant breaking loose, creating a pedestrian safety hazard.

APPLICATION SITUATION

Expansion joints on brick floors

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How Leaflet FPA-6.

BELZONA FACTS

All expansion joints were sealed with approximately \$30,000 in Belzona product. Nearly ten years after, they are still in good shape.

INDUSTRY

General Industry

LOCATION

Corporate offices of Tennessee power company

APPLICATION DATE

1988

PRODUCTS

Belzona 2221 (MP Fluid Elastomer)

SUBSTRATE

Brick

PHOTOS

1. The application was carried out with the in-house maintenance staff of the power company. Closed cell foam backer rod being inserted.
2. Applying Belzona 2221.
3. Expansion joint sealed.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

