



KERBS FIXED IN PLACE WITH BELZONA

ID: 6203



PROBLEM

Delivery of some shipping containers carrying tools and equipment for the refurbishment of the centre had caused damage to the demarcation kerbs around the car park.

APPLICATION SITUATION

Shopping Centre car Park

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet FPA-11. The damaged sections of kerb were removed to allow the substrate to be cleaned and prepared before bonding the original kerbs back into place using the Belzona 4111 system.

BELZONA FACTS

Belzona 4000 series products were chosen for their high strength, durability, ease of use and fast curing properties which allowed for the repairs to be carried out quickly using the original kerbs without the need for extensive reconstruction and only minimal disruption to traffic flow.

INDUSTRY

Buildings & Structures

LOCATION

Shopping centre, Brisbane, Queensland, Australia

APPLICATION DATE

June 2013

PRODUCTS

Belzona 4111 (Magma Quartz)

SUBSTRATE

Concrete

PHOTOS

1. The damaged/missing kerbs 2. Belzona 4111 applied to underside of kerb 3. Belzona 4111 applied to floor prior to refitting the kerb 4. Kerbs permanently back in position

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

