

NEW KERB CREATED WITH BELZONA

ID: 6204



PROBLEM

The existing kerb had been damaged and needed to be repaired / replaced

APPLICATION SITUATION

Shopping Centre car Park.

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona System Leaflet FPA-1. After removing damaged kerb an MDF former was installed and Belzona 4111 applied into the former to re-create the original kerb profile. Once Belzona 4111 had sufficiently cured, the former was removed leaving the perfectly formed kerb.

BELZONA FACTS

The Belzona 4111 was chosen because it allowed for the repair to be carried out quickly and easily in one application without the need for major construction works, minimising disruption to the car park.

INDUSTRY

Buildings & Structures

LOCATION

shopping centre, Brisbane, Queensland, Australia

APPLICATION DATE

June 2013

PRODUCTS

Belzona 4111 (Magma Quartz)

SUBSTRATE

Concrete

PHOTOS

1. The damaged missing nosings 2. Former being constructed 3. The former in position ready for repair to take place 4. The finished application, after removal of former, ready for painting

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

