

BELZONA REPAIRS SWIMMING POOL

ID: 6253



PROBLEM

A significant water leak from the pool due to the crack of the concrete.

APPLICATION SITUATION

Concrete crack on the bottom of the swimming pool .

APPLICATION METHOD

The Application was carried out in accordance with Belzona Know-How FPA 1

BELZONA FACTS

Previous repairs to other materials did not cause inhibition of the leak. Removed loose and wet concrete parts. The entire exposed concrete was painted Belzona4151. At the end of applied Belzona 4111.

INDUSTRY

LOCATION

Kwidzyn (Poland)

APPLICATION DATE

May 2011

PRODUCTS

Belzona 4151 (Resin)

Belzona 4911 (TX Conditioner)

Belzona 4111 (Magma-Quartz)

SUBSTRATE

concrete

PHOTOS

1. General view of the damaged bases
2. The bottom of the pool after the application of Belzona 4151
3. Supplementing concrete damage - Belzona 4111.
- 4.General view of the swimming pool.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

