

BELZONA CURES DRUG FACTORY FLOOR

ID: 6255



PROBLEM

The cracks collect a lot of bacteria and contaminants creating a serious hygiene issue.

APPLICATION SITUATION

Very damaged and cracked concrete floor in the medicines factory.

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflets FPA-1 and FPA-3.

BELZONA FACTS

Solvent free Belzona system enabled floor repairs to be carried out with minimal disruption to production in adjoining areas. Belzona repair provided a smooth, easy clean, hygienic surface suitable for pharmaceutical production.

INDUSTRY

Food & Drink

LOCATION

Pharmaceutical company, Warsaw, Poland

APPLICATION DATE

June 2013

PRODUCTS

Belzona 4111 (Magma Quartz)

Belzona 5811 (Immersion Grade)

SUBSTRATE

concrete

PHOTOS

1. View of damaged warehouse floor 2.
Close up of the cracked concrete 3.
and 4. The floor after application of Belzona 5811

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.