

PUMP REPAIR AND EFFICIENCY ENHANCEMENT WITH BELZONA

ID: 626



PROBLEM

The pump had significant corrosion.

APPLICATION SITUATION

Large horizontal split case pump housing

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet CEP-10.

BELZONA FACTS

The client realised a 7% increase in efficiency.

INDUSTRY

Fluid Flow

LOCATION

Drinking Water Supplier, Portugal

APPLICATION DATE

February 2004

PRODUCTS

Belzona 1111 (Super Metal)
Belzona 1341 (Supermetalgilde)

SUBSTRATE

Brass and cast iron

PHOTOS

1. The severe localised corrosion
2. Application of Belzona 1111
3. The completed repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

