

BELZONA ROOF REPAIRS AT PROMINENT RETAILER

ID: 6271



PROBLEM

Leaking joints were causing disruption to staff and shoppers at this high end department store.

APPLICATION SITUATION

Roof leaks on a Department store roof.

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet RPA-1. A fully reinforced Belzona 3111 system was applied to span across the joints.

BELZONA FACTS

Belzona 3111 was chosen because it only needed to be applied at the problem joints so making application quick and simple.

INDUSTRY

Commercial Facilities

LOCATION

Department store, NSW, Sydney

APPLICATION DATE

December 2004

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Concrete

PHOTOS

1. The leaking joints 2. Masking off before starting application 3. Conditioned joints 4. Application of Belzona 3111 in progress

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

