

BELZONA SEALS PARAPET WALL

ID: 6276



PROBLEM

Ingress of water into the building below caused by failed sealant on the parapet wall joints.

APPLICATION SITUATION

Parapet wall on the roof of a Shopping Centre

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet RPA-8. A fully reinforced Belzona 3111 system was applied to bridge between roof deck and wall.

BELZONA FACTS

Belzona 3111 was used for its easy application and ability to seal multiple substrates whilst coping with the differential movement present at the flashing.

INDUSTRY

Commercial Facilities

LOCATION

Shopping Centre, NSW, Australia

APPLICATION DATE

July 2004

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Concrete & Asphalt

PHOTOS

1. Preparation in progress 2. Surface Conditioner applied 3. completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

