

BELZONA SAFETY FLOORING AROUND MIXER

ID: 6279



PROBLEM

The floor was covered with a rubber lining which was very slippery when Glycol was spilt on it. One worker had broken a foot after slipping on the floor.

APPLICATION SITUATION

The floor lined with rubber lining around a mixer handling Glycol and other additives.

APPLICATION METHOD

The application was carried out in accordance with Belzona System Leaflet FPA-8. After removing rubber sheets and cleaning the concrete, Belzona 4111 was used to level the concrete before applying the Belzona 4411 non-slip system.

BELZONA FACTS

After application of Belzona 4411 floor is safe and there have been no more slips. Belzona 4411 provides a chemical resistant surface that makes clean-up of spills easy whilst providing a positive grip surface to prevent slips.

INDUSTRY

General Industry

LOCATION

Ceramics producer, Gliwice, Poland

APPLICATION DATE

May 2011

PRODUCTS

Belzona 4111 (Magma Quartz)
Belzona 4411 (Granogrip)

SUBSTRATE

Concrete

PHOTOS

1. Grinding concrete floor
2. Repair of damage and filling cavities with Belzona 4111
3. Application of Belzona 4411
4. General view of the floor after application of Belzona 4411 system

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

