


BELZONA RESTORES CORRODED PUMP HOUSING

ID: 628



PROBLEM

The pump had extensive corrosion.

APPLICATION SITUATION

Horizontal split case centrifugal water distribution pump.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet CEP-5 & CEP-10.

BELZONA FACTS

Another, similar pump, had been coated with Belzona 6 years previously and recent inspection found it to be excellent condition so client had no hesitation in specifying Belzona again.

INDUSTRY

General Industry

LOCATION

Drinking water supplier, Lisbon region, Portugal

APPLICATION DATE

November 2004

PRODUCTS

Belzona 1341 (Supermetalgilde)

SUBSTRATE

Cast iron

PHOTOS

1. Corroded pump housing
2. Corroded pump outlet
3. Application of Belzona 1341
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

