

BELZONA SEALS ROOF SKYLIGHTS

ID: 6286



PROBLEM

Large leaks occurred into offices below whenever it rains.

APPLICATION SITUATION

Corrugated sheet metal roof containing several skylights.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-3.

BELZONA FACTS

Under the leaky roof was office manager. After application of Belzona 3111 for the first time the director was in a good mood! Belzona 3111 system is ideal for sealing around complex structures and bonds to a wide range of dissimilar substrates.

INDUSTRY

Buildings & Structures

LOCATION

Office building, Silesia, Poland

APPLICATION DATE

August 2011

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Metal and polycarbonate

PHOTOS

1. Skylight prepared for repair 2. Skylight after repair with Belzona 3111 3. Other sealed skylights 4. The roof in 2016 still good with Belzona 3111

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

