




BELZONA RESURFACES WATER SUPPLY TROUGH AT OUTDOOR SWIMMING POOL

ID: 6287



PROBLEM

Over period of many years, the pool chemicals had attacked the concrete channel leaving the aggregate exposed. Ultimately loose aggregate would get into the pumps and damage them.

APPLICATION SITUATION

The concrete surface.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

BELZONA FACTS

Based on a similar previous application which had lasted beyond 5 years with no maintenance the green was given to refurbish a similar pool within the same municipality

INDUSTRY

Buildings & Structures

LOCATION

Coquitlam, BC

APPLICATION DATE

April 2015

PRODUCTS

Belzona 4111 (Magma-Quartz)

SUBSTRATE

Concrete

PHOTOS

1. View of water supply channel
2. View of the eroded surface that need to be resurfaced
3. Resurfacing with Belzona 4111 in progress.
4. Completed supply channel

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

