

BELZONA SEALS LEAK IN UNDERWATER OBSERVATION WINDOW

ID: 6289



PROBLEM

The underwater observation window had developed a leak.

APPLICATION SITUATION

A leak on the underwater window.

APPLICATION METHOD

The application was carried out in accordance with a modified Belzona Know-How System Leaflet FPA-6. The stainless steel surround was prepared using a grinder to achieve a clean rough profile on the metal surface. After masking off the perimeter, a $\frac{1}{8}$ thick rubber tape was used to create a suitable clearance on the inside of the window-sufficient to clear the screw heads.

BELZONA FACTS

Belzona Elastomer had been used successfully in similar situation.

INDUSTRY

Buildings & Structures

LOCATION

Vancouver, BC

APPLICATION DATE

March 2015

PRODUCTS

Belzona 2211 (MP Hi-Build Elastomer)

SUBSTRATE

Stainless Steel/ Butyl Rubber

PHOTOS

1. View of observation window
2. Metal surface prepared
3. Perimeter of the window masked off
4. Completed application with all tapes removed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

