


BELZONA REPLACES INDOOR SWIMMING POOL EXPANSION JOINTS

ID: 6292



PROBLEM

Existing expansion joint material had failed.

APPLICATION SITUATION

The expansion joints of a pool

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-6. The surface was grinded to a clean dry porous finish, then Belzona 2221 was injected into the joint and allowed to settle and cure.

BELZONA FACTS

This was the 3rd Belzona Elastomer expansion joint application. The original application completed in 2007 which it lasted for more than 8 years before it required any further maintenance.

INDUSTRY

Buildings & Structures

LOCATION

Tsawwassen, BC

APPLICATION DATE

August 2015

PRODUCTS

Belzona 2221 (MP Fluid Elastomer)

SUBSTRATE

Concrete/ Tile

PHOTOS

1. Joint preparation completed by grinding the expansion joint slot to a clean dry porous finish
2. Joint masked off to ensure a neat and tidy finish
3. Application of Belzona 2221
4. Completed application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

