

# 80 TONNE BULLDOZER TRACKS-NO PROBLEM FOR BELZONA

ID: 6296



## PROBLEM

The workshop floor had been damaged by the caterpillar tracks making 180 degree turns tearing up the concrete.

## APPLICATION SITUATION

Workshop Floor where large, 80 Tonne bulldozers and excavators are maintained.

## APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet FPA-1. The floor area was badly damaged and had to be dug out to provide a suitable surface for rebuilding. Once done the area was rebuilt to the original level using the Belzona 4111 system.

## BELZONA FACTS

Belzona 4111 was chosen after a successful trial area proved the extremely hard wearing and high load bearing properties of the product. The fast curing nature of the material was also a consideration as it meant the workshop could remain operational during repairs.

## INDUSTRY

General Industry

## LOCATION

Workshop floor, Kwinana, Western Australia

## APPLICATION DATE

November 2015

## PRODUCTS

Belzona 4111 (Magma Quartz)

## SUBSTRATE

Reinforced Concrete

## PHOTOS

1. The damaged concrete floor 2. Another area of damage 3. Close up of the repaired area 4. View of the workshop showing repairs

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

[www.belzona.com](http://www.belzona.com)



Copyright © 1952-2026 Belzona International Limited.