

BELZONA ROOF REPAIR, EIGHT YEARS AND HOLDING

ID: 63



PROBLEM

Severe water leakage

APPLICATION SITUATION

Expansion joints of slab roof above generators

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How Leaflet RPA-1.

BELZONA FACTS

Eight years ago, approximately \$30,000 in Belzona product was used and solved the leakage problem. Based on the success, the plant recently purchased \$50,000 of material to fix the other side of the roof, basically to seal the joints and cracks in the concrete slab.

INDUSTRY

Power

LOCATION

Power Plant in Georgia

APPLICATION DATE

1989

PRODUCTS

Belzona 3111 (Flexible Membrane)
Belzona 3911 (PSC Surface Conditioner)

SUBSTRATE

Concrete

PHOTOS

1. Joints were leaking.
2. Belzona 3111 applied 8 years ago and still preventing leakage.
3. Another view of the roof.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

