

TANK ROOF REPAIR

ID: 631



PROBLEM

The roof was badly deteriorated. Concrete cracked due to the very hot and dry environment, as well as strong UV attack and potable water was being contaminated.

APPLICATION SITUATION

Drinking water supply tank

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How Systems Leaflet RPA-1.

BELZONA FACTS

The client was impressed by the performance of Belzona on other applications in the region. The products excellent UV resistance, weatherproofing properties and long lasting life meant that this was an economical long term repair. In 2011, the application was inspected and found in good condition. Customer is very satisfied with this solution.

INDUSTRY

Water / Wastewater

LOCATION

Drinking water supplier, Portugal

APPLICATION DATE

August 2004

PRODUCTS

Belzona 3111 (Flexible Membrane)
Belzona 9311 (Reinforcing Sheet) Belzona
3911 (PSC Surface Conditioner)

SUBSTRATE

Concrete

PHOTOS

1. Damaged tank roof in 2004 2.
Preparation of roof surface in 2004 3.
Application of Belzona in 2004 4. The
application is still in good condition in
2011

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

