

BELZONA PROVIDES FOOD FOR THOUGHT

ID: 632



PROBLEM

Several holes in the weld seams and isolated pinholes. All surfaces showed signs of corrosion and existing paint work was cracked and peeling.

APPLICATION SITUATION

Large exhaust duct bend

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets VPF-1 and VPF-2.

BELZONA FACTS

This system was selected to provide long term protection in the wet and polluted atmospheric conditions. This was coupled with its excellent appearance. The application is still performing well after six years.

INDUSTRY

General Industry

LOCATION

Food Processing Plant, Manchester UK

APPLICATION DATE

July 1999

PRODUCTS

Belzona 1111 (Super Metal)

Belzona 6111 (Liquid Anode)

Belzona 5111 (Ceramic Cladding)

SUBSTRATE

Mild Steel

PHOTOS

1. Exhaust duct outlet
2. Exhaust duct bend
3. Exhaust duct repaired

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

