

BELZONA REPAIRS HOLES WITH BULKFILL AND MAGMA QUARTZ

ID: 6324



PROBLEM

Due to continuous forklift traffic holes had formed causing an issue in operations.

APPLICATION SITUATION

Forklift traffic over control and expansion joint areas.

APPLICATION METHOD

The holes were cleaned out and filled with Belzona 4124. Once the holes were filled, it was top coated with Belzona 4111. FPA-1 System Leaflet was followed.

BELZONA FACTS

Customer saved a lot of money because there is a tunnel under the areas where the repair was done. Concrete was an option, but it would be a long and costly repair, and would eventually fail again. It took 1 day of labor to do the work. This Belzona system was used because it is proven to work and last a long, long time.

INDUSTRY

Buildings & Structures

LOCATION

Truck Part Manufacturer, NC, USA

APPLICATION DATE

June 2016

PRODUCTS

Belzona 4111 (Magma-Quartz)
Belzona 4124 (Bulkfill)

SUBSTRATE

Concrete

PHOTOS

1. Preparing hole by removing loose material
2. After preparation
3. Bulkfilling with Belzona 4124
4. Top coated with Belzona 4111

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

