

BELZONA PROTECTS LISTED BUILDING

ID: 633



PROBLEM

Traffic, pollution and grime had discolored the facade of the building.

APPLICATION SITUATION

Grade 1 Listed Building

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet WPA-1.

BELZONA FACTS

Eleven years previously this building had been coated in Belzona® 3111 to stop external water and damp ingress. After inspection it was revealed that although it had become very grimy the Belzona coating was still in very good condition and would continue to function. The client decided that rather than just cleaning it, a self cleaning coating from Belzona would be better. The building is still looking good four years later.

INDUSTRY

Buildings & Structures

LOCATION

Local Council Contractors, Liverpool UK

APPLICATION DATE

September 2001

PRODUCTS

Belzona 5151 (Hi-Build Cladding)
Belzona 3111 (Flexible Membrane)

SUBSTRATE

Masonry coated with Belzona® 3111

PHOTOS

1. Before application
2. During application, surface conditioned
3. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

