

LEAKING FLANGE COUPLINGS SEALED WITH BELZONA

ID: 6331



PROBLEM

After several years in operation and due to vibration, oil started to leak from some couplings leading to pollution and loss of efficiency.

APPLICATION SITUATION

Flange couplings at a paper press machine

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet TCC-1 for sealing cracks, porous welds, bolted and riveted joints. The surface was cleaned with Acetone and abraded using the MBX bristle blaster. Belzona 1161 was applied in conjunction with Belzona 9341 to seal the leak.

BELZONA FACTS

The customer needed a fast solution to solve the problem. Belzona repair was quick and cost-effective, eliminating any downtime.

INDUSTRY

Pulp & Paper

LOCATION

Tuscany, Italy

APPLICATION DATE

December 2010

PRODUCTS

Belzona 1161 (Super UW-Metal) Belzona 9341 (Reinforcement Tape)

SUBSTRATE

Carbon Steel

PHOTOS

1. Leaking flange coupling 2. Surface preparation 3. Belzona repair 4. Belzona repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com


BELZONA

Copyright © 1952-2026 Belzona International Limited.