

BELZONA PROTECTS MAIN ENTRY OF APARTMENT

ID: 6332



PROBLEM

The apartment complex recently had concrete replacement on its clubhouse, including the main entry, sidewalks, and curbing. The management was worried that the new concrete would not last unless protected. There were concerns of inclement weather and subsequent ice melts and salts being used, staining from watering the plants and constant pedestrian traffic and deliveries.

APPLICATION SITUATION

Main entry of apartment

APPLICATION METHOD

The concrete was prepared via diamond grinding and vacuuming, followed by the application of Belzona 5231 broadcasted with excess of custom blended color flake. A top coat of Belzona 5233 clear for sealing. A modified FPA-8 system leaflet was followed.

BELZONA FACTS

The project was accomplished during a normal shutdown of the office, Sunday, and opened to normal traffic the following morning providing a very attractive, safe, and durable finish to protect the newly replaced concrete.

INDUSTRY

Buildings & Structures

LOCATION

Property Management, Kansas City, Missouri

APPLICATION DATE

May 2016

PRODUCTS

Belzona 5231 (SG Laminate) Belzona 5233

SUBSTRATE

Concrete

PHOTOS

1. The original appearance of the entry with the planters and floor mats removed 2. Diamond grinding under way 3. Application of Belzona 5231 4. Completed application of 5231/locally sourced aggregate/5233

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

