


QUARRY BELT REPAIR

ID: 634



PROBLEM

600mm (23inch) tear in the belt

APPLICATION SITUATION

Sand Belt

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-1.

BELZONA FACTS

The belt performed well until the plants closing in 2004.

INDUSTRY

Mining & Quarrying

LOCATION

Local Depot, Manchester UK

APPLICATION DATE

June 2000

PRODUCTS

Belzona® 2311 (SR Elastomer)

SUBSTRATE

Rubber

PHOTOS

Large sand belt 600mm gash in the belt

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

