

BELZONA REPAIR ON CONCRETE DAM

ID: 6343



PROBLEM

The damaged area is partially submerged and the entire area frequently wet from wave action. The dam has been declared a historic site so repair materials need to closely match the appearance of the original material.

APPLICATION SITUATION

The face of the 100 yr old concrete hydro dam was damaged at the waterline due to ice and wave action.

APPLICATION METHOD

A temporary dyke was created around the area needing repair. Compressed air was used to blow the standing water off the damaged area. The surface was prepped with chisels and a bristle blaster. Dust and loose debris were blown off. The 4911 was applied and the repair was made with 4141 to just below the desired finish level. Finally a coat of 4131 was applied to finish the work.

BELZONA FACTS

Belzona was chosen because of its rapid cure, non-shrink and superior adherence characteristics. Magma build was chosen due to the need to work without forms and Magma Screed for color and finish.

INDUSTRY

Buildings & Structures

LOCATION

Michigan, USA

APPLICATION DATE

September 2016

PRODUCTS

Belzona 4131 (Magma-Screed)

Belzona 4141 (Magma-Build)

Belzona 4911 (Magma TX Conditioner)

SUBSTRATE

Concrete

PHOTOS

1. Damaged area at waterline
2. Work in process.
3. Finished repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

