

BELZONA PROTECTS NEW BUILT WATER FILTERS

ID: 6369



PROBLEM

New water debris filters required protection against erosion-corrosion at temperatures up to 130C

APPLICATION SITUATION

Internal coating of three water debris filters

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How-System Leaflet TCC-5.

BELZONA FACTS

Customer was originally coating filters with rubber lining but was looking for an alternative cost effective and easy to maintain solution. Belzona coating will allow customer to carry out quicker and on-site maintenance which will save significant downtime.

INDUSTRY

Water / Wastewater

LOCATION

Desalination Plant, Saudi Arabia

APPLICATION DATE

August 2016

PRODUCTS

Belzona 1391T

SUBSTRATE

Carbon Steel

PHOTOS

1. Stripe coating with Belzona 1391T
2. First coat of Belzona 1391T applied
3. The three filters fully protected with 2nd coat of Belzona 1391T

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

