


BELZONA PROTECTS AGAINST ACID ATTACK

ID: 637



PROBLEM

Hydrochloric acid was seeping into a nearby water course. The problem was tracked down to a sump which had a hole in it, hydrochloric acid was leaking through and eating through the underlying concrete.

APPLICATION SITUATION

Acid waste sump

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet TCC-9. Damaged concrete was rebuilt and levelled with Belzona 4111 before coating with Belzona 4311.

BELZONA FACTS

Belzona was initially chosen because it was a long term solution that could be applied during the available 3 day factory shut down. The client was delighted with Belzona going the extra mile to complete the unscheduled works within the allowed time frame. The sump is still performing as expected preventing any further seeping into the water course.

INDUSTRY

Chemical & Petrochemical

LOCATION

Chemical Plant, Cheshire, UK

APPLICATION DATE

March 2003

PRODUCTS

Belzona 4311 (Magma CR1)

Belzona 4111 (Magma Quartz)

SUBSTRATE

Concrete

PHOTOS

1. The extent of the problem
2. Belzona 4111 fills the hole
3. Sump rebuilt using Belzona 4111
4. Coated with Belzona 4311 to protect from acid attack

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

