

BELZONA 1391 PROTECTS NEW PIPEWORK

ID: 638



PROBLEM

Moisture in the system creates carbonic acid that corrodes the pipework.

APPLICATION SITUATION

New gas scrubber pipework

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-2.

BELZONA FACTS

The coating of Belzona® 1391 onto the new carbon steel pipework was chosen over traditional cast iron construction as a more cost effective and long term solution. The application continues to perform as expected.

INDUSTRY

Chemical & Petrochemical

LOCATION

Chemical plant, Cheshire UK

APPLICATION DATE

August 2003

PRODUCTS

Belzona 1391 (Ceramic HT Metal)

SUBSTRATE

Carbon steel

PHOTOS

1. The problem
2. Application of Belzona 1391
3. Finished job
4. High quality finish clearly visible

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

