

BELZONA WEATHERPROOFS THE ROOF AND SAVES ELECTRICAL EQUIPMENT ON OFFSHORE PLATFORM

ID: 6381



PROBLEM

Water leaking into a metal building from existing patches on the roof and porous weld seams. Other types of epoxy repairs were tried, but failed due to the harsh offshore weather.

APPLICATION SITUATION

Metal building with leaking roof on offshore platform. Electrical equipment housings inside building are getting corrosion damage.

APPLICATION METHOD

Belzona 1121 is used to seal porous welds and fill gaps in existing welded metal patches. Belzona 5811 is used to seal all surfaces. Belzona 5111 is used as a top coat to provide durable weather resistance.

BELZONA FACTS

Building replacement was not an option due to very high costs.

INDUSTRY

Oil & Gas

LOCATION

Gulf of Mexico, USA

APPLICATION DATE

September 2016

PRODUCTS

Belzona 1121 (Super XL-Metal)
Belzona 5111 (Ceramic Cladding)
Belzona 5811 (Immersion Grade)

SUBSTRATE

Carbon steel

PHOTOS

1. After abrasive blasting some metal patches were loose.
2. Metal plate perimeter and holes sealed with 1121.
3. Spray application of 5811 beige and non-skid aggregate.
4. Spray application of 5111 gray top coat.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

