

BELZONA SUPERWRAP II REPAIRS DRAIN LINES ON DEEPWATER PLATFORM

ID: 6382



PROBLEM

The drain line goes to the sump, which is the lowest point on the platform. If there is any oil spill or runoff, it could potentially get into the water.

APPLICATION SITUATION

Deepwater platform has 17 areas on drain line that need repair. The repair needed to be ASME compliant.

APPLICATION METHOD

Being the lowest drain point on the platform, the work had to be carried out by a rope access crew.

BELZONA FACTS

Replacing the drain line would require hazardous hot work and a platform-wide shut in. An unplanned shut in would cost the client \$3M per day.

INDUSTRY

Oil & Gas

LOCATION

Gulf of Mexico, USA

APPLICATION DATE

July 2016

PRODUCTS

Belzona 1111 (Super Metal)
Belzona Superwrap II

SUBSTRATE

Carbon steel

PHOTOS

1. Overall view of drain line.
2. Example defect on pipe.
3. Area prepared and Testex profile tape.
4. SuperWrap II installed by rope access.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

