

KEEPING AFLOAT WITH BELZONA

ID: 639



PROBLEM

Damaged due to collision with other objects such as boats, flotsam etc.

APPLICATION SITUATION

Sponson (An air bag or floatation device) attached to a fast rescue craft.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SOS-12.

BELZONA FACTS

Every repair with Belzona here saves the purchase of a new sponson at a cost of £400.00. The added bonus was that the repairs could be done at sea allowing the rescue craft to remain in service. This method of repair was used until the craft were taken out of service.

INDUSTRY

Oil & Gas

LOCATION

Oil Rig Operator.

APPLICATION DATE

March 2001

PRODUCTS

Belzona® 2311 (SR Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. Surface prepared
2. Area marked up, ready for the Belzona
3. Finished repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

