

BELZONA PULVERIZER SHAFT

ID: 64



PROBLEM

Coal fines work their way underneath the seal fit and cause wear to the shaft.

APPLICATION SITUATION

Pulversizer shaft

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How Leaflet MPT-2.

BELZONA FACTS

Since 1994, several shafts have been done. Less than \$400 in Belzona product saved the plant one week of downtime.

INDUSTRY

Power

LOCATION

Fossil Power Plant in Alabama

APPLICATION DATE

1994

PRODUCTS

Belzona 1311 (Ceramic R Metal)

SUBSTRATE

Steel

PHOTOS

1. Sweating oils from the substrate.
2. The split-form molding technique is used.
3. Formers removed, Belzona 1311 ready for dressing down.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

