

BELZONA BULKFILL USED ON LOADING BAY

ID: 6417



PROBLEM

Regular loading and unloading caused severe wear to the surface of the loading bay. A cost effective solution to this ongoing problem was required.

APPLICATION SITUATION

Asphalt covered loading bay to the plasterboard factory.

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflets FPA-1, 2 & 8. After chipping away the damaged asphalt with pneumatic tools, the area was cleaned and prepared, followed by Belzona 4154 to bulk out the area. Belzona 4111 was then used to level the surface and to secure steel plates, previously coated with Belzona 4411 grip system.

BELZONA FACTS

Belse, the Belzona Distributor in Poland, has carried out many similar applications but before the introduction of Belzona 4154 had to use all Belzona 4111. This was considered an expensive option. The introduction of Belzona 4154 allows them to offer an equivalent performing application but at a much better price to the customer with the knowledge that they will receive a long lasting solution to loading bay problems.

INDUSTRY

General Industry

LOCATION

Plasterboard manufacturer, Poland

APPLICATION DATE

December 2016

PRODUCTS

Belzona 4154 (Bulkfill)
Belzona 4111 (Magma Quartz)
Belzona 4411 (Granogrip)

SUBSTRATE

Concrete

PHOTOS

1. Chipping away the existing asphalt 2. Applying Belzona 4411 Grip System to steel plate 3. Applying Belzona 4154 to the large area 4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

