




BELZONA IMPROVES SAFETY WITH GRIP SYSTEM

ID: 6418



PROBLEM

Marble stairs were very slippery, especially in wet conditions.

APPLICATION SITUATION

Factory main entrance steps.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. The steps were marked and the nosing ground with carbide discs. After masking off all the steps, Belzona 4411 was brushed on and sprinkled with Belzona 9221.

BELZONA FACTS

The previous solutions of abrading the nose or stick on strips had proved to be ineffective. Belzona 4411 reduced the potential for accidents as well as creating an aesthetically pleasing finish.

INDUSTRY

Buildings & Structures

LOCATION

Factory, Kirkop, Malta.

APPLICATION DATE

May 2013

PRODUCTS

Belzona 4411 (Granogrip)
Belzona 9221 (Surefoot Aggregate White)

SUBSTRATE

Marble

PHOTOS

1. Abraded nosing resulted in a non-effective solution
2. Nosing ground by carbide discs
3. Area Masked off
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

