

BELZONA RENEWS 40 METRE VERTICAL EXPANSION JOINT

ID: 6420



PROBLEM

The existing joint material had failed resulting in a route for water ingress inside the building. Some of the offices could not be used because of this leak.

APPLICATION SITUATION

Failed expansion joint at industrial building

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet WPA-3 and WPA-9. The existing joint material was removed and the edges were rebuilt with Belzona 4141. Belzona 2211 was applied to seal the joint. To further seal and encapsulate the joint, bridging tape was applied over the expansion joint prior to the application of the Belzona 3111 system. This also provided an aesthetically pleasing finish.

BELZONA FACTS

Belzona 4141 provides a durable joint nosing, whilst Belzona 2211 provides a highly elastic long-term waterproof seal in the joint. The Client ordered two more expansion joint repairs after this one.

INDUSTRY

Buildings & Structures

LOCATION

Industrial unit, Malta

APPLICATION DATE

August 2014.

PRODUCTS

Belzona 4141 (Magma-Build).
Belzona 2211 (MP Hi-Build elastomer).
Belzona 3111 (Flexible Membrane).

SUBSTRATE

Concrete

PHOTOS

1. Existing joint material removed and cleaned.
2. Masking and conditioned.
3. Application of Belzona 2211 Elastomer.
4. Completed application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

